



TS26, 27, 28, 29, 47 (BF254) can be replaced by BF494
TS32', 32'' (BC109C Spec.) can be replaced by BC549C spec.