



For /10 and /11 version TS402 (BC107B) can be replaced by BC547B  
 TS403, 404, 406 (BC307) can be replaced by BC557  
 For /11 version TS401 (BDY38) can be replaced by BD181